## Material Safety Data Sheet

May be used to comply with OSHA'S Hazard Communication Standard 29 CFR 1910.1200. Standard must be consulted for specific requirements.

## MOTHERS® POLISHES • WAXES • CLEANERS

5456 Industrial Drive

Huntington Beach, Ca. 92649

Telephone No. for Information: 714-891-3364
Fax No. 714-893-1827

Date Prepared

5/3/02

CALIFORNIA GOLD NATURAL FORMULA	_PART NO.	05550
PASTE WAX		
	_	

HAZARDOUS INGREDIENTS	/IDENTITY INFORMATION	l		
Hazardous Components (Specific Chemi	cal Identity; Common Name(s) OSI	HA PEL ACGIH TLV Other Limits % (optional)		
ALIPHATIC SOLVENT	CAS# 64741-65-7	500P/Ma 500P/Ma		
KEROSENE	CAS # 8008-20-6	500P/Ma 500P/Ma		
TURPENTINE	CAS 3 MX800 6642	100 PPM		
PHYSICAL/CHEMICAL CHA	RACTERISTICS			
Boiling Point		Specific Gravity (H2O = 1)	N/A	
Vapor Pressure (mm Hg.)	N/D	Melting Point	130° F	
Vapor Density (air = 1)	N/D	Evaporation Rate (Butyl Acetate = 1)	N/D	
Solubility in Water	N/D			
Appearance and Odor	YELLOW PASTE WAX - LOW PERFUME ODOR			
FIRE AND EXPLOSION HAZ	ARD DATA			
Flash Point (Method Used)	133°F TAG OC			
Extinguishing Media	CO2 FOAM, DRY CHEMICAL			
Special Fire Fighting Proced				
	TREAT AS SO	LVENT FIRE		
Unusual Fire and Explosion I				
NONE DETERMINED				

REACTIVITY DATA				PART NO.	5550
 		la m			
STABILITY Unstable		Conditions to	Avoid		
Stable Incompatibility ( Materia	X (a to Avoid)				
Incompatibility (Materia	is to Avoid)				
Hazardous Decompositio	n or By-Prod	ucts			
Hazardous YE\$		Conditions to	avoid		
Polymerization NO	Х				
-	•				
HEALTH HAZARD DATA	<b>L</b>				
				_	
Route(s) of Entry		Inhalation?	Skin?	Ingestion?	1
11 11 11 1 / 4 .	101 : )		X	X	
Health Hazards (Acute a	nd Chronic)				
Carcinogenicity:	NTP?	IARC Monogra	nho?	OSHA Regulated	2
Carcinogenicity.		STABLISHED	apns:	NO	·
Signs and Symptoms of		STABLISTIED		INO	
olgris and dymptoms of	Exposure				
Medical Conditions Gener	rallv		NONE ESTABLI	SHED	
Aggravated by Exposure	-			<u> </u>	
Emergency and First Aid		ı	INGESTION: DO	O NOT INDUCE VOM	ITING, CONTACT
PHYSCIAN IMMEDIATELY.					
PHYSCIAN.				·	
PRECAUTIONS FOR SAFI	E HANDLING	AND USE			
Steps to Be Taken in Cas			oill <u>ed</u>		
SCRAPE UP AND WASH A	AREA THORO	UGHLY			
Waste Disposal Method	0000 HO TO	0011111110			
LAND FILL OR BURN ACC					
Precautions to Be Taken	in Handling a	and Storing			
NONE DETERMINED Other Precautions					
STORE BELOW 120° F					
Control Measures					
Control Measures					
  Respiratory Protection (	Specify Type	)			
Ventilation Local Exhaus		, T			
Mechanical (		Х			
Protective Gloves		GLOVES	Eye Proctectio	n	SAFETY GOGGLES
Other Protective Clothin	g or Equiptm	ent	N/D		
Work/Hygienic Practices		WASH HANDS	S THOROUGHLY A	SETER USE	